




Fig. 1

2025-10-13 10:09:54 - 03:53



2051ED 45966001



2051ED 4896600T




Fig 4A






Fig 4B



Hand-drawn schematic diagram of a square device 500. The device has four sides, each with a series of pins or contacts. The top side is labeled 542, the right side 541, the bottom side 544, and the left side 543. Each side has a label 525 pointing to the pins. A label 510 points to the bottom-right corner. An arrow points from the top-right corner towards the label 500.

A hand-drawn schematic diagram of a square frame assembly. The diagram shows a central square frame with four corner joints. The frame is composed of four main sections, each labeled with a reference numeral: 524 (top-left), 522 (top-right), 532 (bottom-right), and 534 (bottom-left). The frame is supported by four corner brackets, labeled 542, 530, 541, and 543. The frame is surrounded by a series of small rectangular blocks, labeled 523, 522, 532, and 534. The frame is also surrounded by a series of small rectangular blocks, labeled 523, 522, 532, and 534. The frame is also surrounded by a series of small rectangular blocks, labeled 523, 522, 532, and 534. The frame is also surrounded by a series of small rectangular blocks, labeled 523, 522, 532, and 534.

Fig. 5B









10099684.034502






Fig. 9

4099604 031507



2025 FEB 10 10:55:00







FIG. 11A



FIG. 11B



Pitched Landing



4896600T 0504 4896600T



20250719 195600T 1009664 034502




Fig. 13A




Fig. 13B




FIG. 14




FIG. 15

2025 FEB 03 15:03